
## **OPS Briefing**

0900 January 13, 2014







Air Monitoring Location/Data Map - 1/12/14 - 14;20 hours Charleston, WV Chemical Leak - Etowah, West Virginia


Map By: WFH

Date Modified: 01/12/2014 Scale: 1.1,682



Source: Base Layers procured from ESRI Online Services

Air Monitoring Results from field screening using START TVA-1000 FID unit. Results are approximate due to response factor relationship, wind, and other potential interferences.





Storm drain below the second containment of tank farm

## **Example of Fill below Tank Farm**

The yellow brick seen in this picture is just one layer of fill used.

- •There is a layer of red brick from demolished buildings
- •Some tile from buildings are used
- •The secondary containment does have a clay liner below the fill and gravel layers

•Freedom Industries will be drilling two holes to look at what the layers of fill are specifically and the depth of each, once the issue with marking gas lines is resolved.

